




500LTS2S30 Pneumatic Lift Desk Assembly Instructions


























Maintenance!

Melamine & Lacquer surfaces: Clean using a mild non detergent soap solution and wipe off excess with a dry soft cloth. Avoid placing sharp items directly on surface.

Aluminum and other metal parts: Clean using a mild non detergent soap solution and wipe off with a clean damp cloth. Use rubbing alcohol for stubborn stains.

Never use solvents for cleaning furniture.

Location: Avoid placing furniture in moist areas or in direct sunlight.



Tel.: 1 800 361-6000 Tel.: 1 800 619-5446

UNITED STATES Fax: 1 800 363-0193 Fax: 1 800 876-7454



Tel.:1-866-440-0448 ergoinfo@richelieu.com www.richelieuergo.com